Order No.: DD+DIS187.01E

1 piece UPEJK MA1

ADC System Components

Type 4406

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
X				**X**	

Please file this document in section 13 of your technical documentation

PRID 1.2.09 Software available now

1 General Information

PRID 1.2.09 offers a solution for the "Study UID" problem (Patient images associated with incorrect patient demographic information; see FSB No.8:, DD+DIS155.01E).

Therefore, the upgrade to PRID 1.2.09 is a must - modification

2 Main Changes in PRID 1.2.09

- Patch which prevents that an image could get wrong patient or study data assigned.
- PRID 1.2.09 supports the new options **Direct ID** and **Fast Preview (Precheck)**.
  Requirements for these options:
  - PRID 1.2.09 (or higher) installed on the PRID –Station
  - COP_1308 / SOL1302 (or higher) installed on the digitizer
  - Direct ID / Fast Preview license switched on

  For detailed information on Direct ID and Fast Preview see DD+DIS081.01E (part of the upgrade kit).

3 Order Number

EB+44060004 PRID 1.2.09 + SOL_1302, incl. Documentation + COP_1308, incl. Documentation

printed in Germany 08 / 2001

AGFA